





Tips and Terms of Use:

- Keep the bag dry. Prolonged exposure to moisture may cause deformation.
- Avoid overloading the bag to prevent wrinkles, deformation, or surface cracking.
 Do not expose the bag to direct sunlight, excessive heat, or chemical
- solvents.
- Keep metal accessories away from humid or salty environments to prevent oxidation.
- Store the bag in a dry, well-ventilated area.
- Clean with a soft brush or cotton cloth using appropriate materials.
- 7. Do not machine wash, as this may deform the bag and oxidise metal parts.

Warranty conditions

- Calumet PRIME Bags are covered by a 5-year limited warranty, effective from the date of purchase. The warranty covers defects in materials and workmanship under normal use and care, as outlined in the care instructions.
- Natural wear and colour fading after long time sun exposure are not quality problem/defects.





SLING 7L

Exterior Dimensions: 31x13x22.5cm

Interior Dimensions: 29.5x11.5x20.5cm

Weight: 0.7kg



Website: www.calumet.info



Manuals: www.calumet.info/manuals

Mail us: support@calumet.info

Manufacturer: Sansa Europe Sp. z o. o. ul. Wersalska 47/75 Lodz 91-212, Poland

Tips, Warranty & Term of use

PRIME Sling 7L

Information